

DEPARTMENT OF HEALTH SERVICES

RADIOLOGIC HEALTH BRANCH

P.O. BOX 942732, MS-178
SACRAMENTO, CA 94234-7320

(916) 445-0931

January 15, 1999



P.D. Rutherford, Manager
Environmental Remediation
Boeing North American
Rocketdyne division
6633 Canoga Ave.
P.O. Box 7922
Canoga Park, CA 91309-7922

Dear Mr. Rutherford;

The Radiologic Health Branch (RHB) performed a confirmation survey of Building T030 located at the Rocketdyne Santa Susana Field Laboratory. This survey, along with a review of the results of a final survey performed by Rocketdyne and a verification survey performed by ORISE of Building T030, shows that the residual activity levels are well below the release limits specified in DECON1.

Therefore, the Radiologic Health Branch concurs that the Building T030 may be released for use without radiological restrictions.

If you have any questions or need further information please contact Mr. Roger Lupo at (916) 324-3731 or Mr. Steve Hsu at (916) 322-4797.

Sincerely,

A handwritten signature in black ink, appearing to read "Gerard Wong".

Gerard Wong, Ph.D., Chief
Radioactive Material Licensing

000633RC

01-21-99A11:30 RCVB